



WP 310 Installation Instructions

NO MOUNTING MATERIAL IS PROVIDED, PLEASE ENGAGE PROFESSIONAL INSTALLER SHOULD YOU DON'T KNOW HOW TO INSTALL OR CALL LOCAL DEALER FOR ASSISTANCE. MAKE SURE THAT THE WALL STRUCTURE CAN SUPPORT AT LEAST FOUR TIMES THE TOTAL WEIGHT OF THE BRACKET AND THE PLASMA.

SCREW LIST		
ITEM	QUANTITY	DESCRIPTION
A	4	M6 X 20MM PAN HEAD
B	16	M6 PLAIN WASHER
C	16	M6 X 10MM PAN HEAD

